Interstate 99 Designation Issues

Vertical Clearance Deficiencies

Disclaimer Statement:
This is not a proposal

This is a display of vertical clearance deficiencies for bridge structures if strict Interstate standards were applied.

Future negotiations with the U.S. Department of Transportation may eliminate some or all of the listed locations.



Tag #	PM	Location Description
104	56.54	Cecil Ave OC
105	56.09	11 Th Ave OC
106	54.48	Woollomes Ave OC
107	52.45	Pond Rd OC
108	49.30	Sherwood Ave OC
109	44.31	Rte 46 OC
110	R30.53	7 Th Std Rd OC
111	27.87	Olive Dr OC
112	27.32	Minkler UP
113	27.01	S99-S204 Connector OC
114	26.78	Airport Dr OC
115	24.99	Truxtun Ave UC
116	24.60	California Ave UC
117	24.11	Palm Ave OC
118	23.52	Brundage Lane OC
119	23.10	Belle Terrace OC
120	22.60	Ming Rd OC
121	22.11	Wilson Rd OC
122	21.96	Wible Rd OC
123	21.60	Planz Rd OC
124	21.08	White Lane OC
125	19.54	Panama Lane OC
126	18.53	Hosking Rd OC
127	15.43	Houghton Rd OC
128	13.41	Route 223/99 Sep
129	10.93	Old Us 99 OC
130	9.30	Herring Rd OC
131	7.29	Sandrini Rd OC
132	L0.75	Route 5/99 Sep

N

Caltrans

December, 2004

District 06 & 10